

## PONTAS MONTADAS - Tipos A e B

Comprim. haste = 40 mm

Diâm. haste = Tipo A = 6,35 mm - Tipo B = 3,17 mm



TIPO	A-1	A-2	A-3	A-4	A-5	A-6	A-11	A-12	A-13	A-14	A-15	A-21	A-22	A-23
DxA (mm)	20x65	25x30	22x70	30x30	20x30	20x30	20x45	18x30	30x30	18x22	6x27	25x25	20x16	20x25



TIPO	A-24	A-25	A-26	A-31	A-32	A-33	A-34	A-35	A-36	A-37	A-38	A-39	A40
DxA (mm)	6x20	25	16	35x25	25x16	25x13	40x10	25x10	40x10	30x6	25x25	20x20	20



TIPO	B-41	B-42	B-43	B-44	B-45	B-46	B-47	B-51	B-52	B-53	B-54	B-55	B-61	B-62
DxA (mm)	16x16	13x20	6x8	6x10	5x8	3x8	3x4	12x20	10x20	6x16	6x13	3x6	20x8	13x10



TIPO	B-63	B-64	B-65	B-70	B-71	B-72	B-73	B-74	B-81	B-82	B-83	B-84	B-90	B-91
DxA (mm)	6x5	6x15	6x3	20x3	16x2,5	13x3	13x13	6x2,5	20x5	13x6	10x4	8x5	13x13	13x16



TIPO	B-92	B-93	B-94	B-95	B-96	B-97	B-98	B-101	B-102	B-103	B-104	B-105	B-106	B-111
DxA (mm)	6x6	5x5	4x2,5	3x4	3x6	2,5x10	2,5x6	16x18	16x13	16x5	8x10	6x6	3x3	12x18



TIPO	B-112	B-113	B-114	B-115	B-121	B-122	B-123	B-124	B-131	B-132	B-133	B-134	B-135	B-136
DxA (mm)	10x13	6x6	6x10	2,5x3	13	10	5	3	13x13	10x13	10x10	8x10	6x13	6x8

## PONTAS MONTADAS - Tipo C



TIPO	D x A (mm)	Haste (mm)	
		C	D
C-141	2,5x4	40	3,17
C-142	2,5x6	40	3,17
C-143	3x3	40	3,17
C-144	3x6	40	3,17
C-145	3x10	40	3,17
C-146	3x13	40	3,17
C-149	4x6	40	3,17
C-151	5x3	40	3,17
C-152	5x6	40	3,17
C-153	5x10	40	3,17
C-154	5x13	40	3,17
C-157	6x2	40	3,17
C-158	6x3	40	3,17
C-159	6x5	40	3,17
C-160	6x6	40	3,17
C-161	6x8	40	3,17
C-162	6x10	40	3,17
C-163	6x13	40	3,17
C-164	6x20	40	3,17
C-165	8x1,5	40	3,17
C-166	8x3	40	3,17
C-167	8x6	40	3,17
C-168	8x8	40	3,17
C-169	8x10	40	3,17
C-170	8x13	40	3,17
C-171	8x20	40	3,17
C-172	10x1,5	40	3,17
C-173	10x3	40	3,17
C-174	10x6	40	3,17
C-175	10x10	40	3,17
C-176	10x13	40	3,17
C-177	10x20	40	3,17
C-178	10x25	40	3,17

TIPO	D x A (mm)	Haste (mm)	
		C	D
C-141	2,5x4	40	3,17
C-142	2,5x6	40	3,17
C-143	3x3	40	3,17
C-144	3x6	40	3,17
C-145	3x10	40	3,17
C-146	3x13	40	3,17
C-149	4x6	40	3,17
C-151	5x3	40	3,17
C-152	5x6	40	3,17
C-153	5x10	40	3,17
C-154	5x13	40	3,17
C-157	6x2	40	3,17
C-158	6x3	40	3,17
C-159	6x5	40	3,17
C-160	6x6	40	3,17
C-161	6x8	40	3,17
C-162	6x10	40	3,17
C-163	6x13	40	3,17
C-164	6x20	40	3,17
C-165	8x1,5	40	3,17
C-166	8x3	40	3,17
C-167	8x6	40	3,17
C-168	8x8	40	3,17
C-169	8x10	40	3,17
C-170	8x13	40	3,17
C-171	8x20	40	3,17
C-172	10x1,5	40	3,17
C-173	10x3	40	3,17
C-174	10x6	40	3,17
C-175	10x10	40	3,17
C-176	10x13	40	3,17
C-177	10x20	40	3,17
C-178	10x25	40	3,17

TIPO	D x A (mm)	Haste (mm)	
		C	D
C-179	10x32	40	3,17
C-181	13x1,5	40	3,17
C-182	13x3	40	3,17
C-183	13x6	40	3,17
C-184	13x10	40	3,17
C-185	13x13	40	3,17
C-186	13x20	40	3,17
C-187	13x25	40	3,17
C-188	13x38	40	6,35
C-189	13x50	40	6,35
C-190	16x1,5	40	3,17
C-191	16x3	40	3,17
C-192	16x6	40	3,17
C-193	16x10	40	3,17
C-194	16x13	40	3,17
C-195	16x20	40	3,17
C-196	16x25	40	6,35
C-197	16x50	40	6,35
C-198	16x65	40	6,35
C-199	20x1,5	40	3,17
C-200	20x3	40	3,17
C-201	20x6	40	3,17
C-202	20x10	40	3,17
C-203	20x13	40	3,17
C-204	20x20	40	3,17
C-205	20x25	40	6,35
C-206	20x33	40	6,35
C-207	20x38	40	6,35
C-208	20x50	40	6,35
C-209	20x65	40	6,35
C-210	22x1,5	40	3,17
C-211	22x3	40	3,17
C-212	22x6	40	3,17